C BEI	LOUISIANA DEPARTMEI Engineering Services MONT WAT	51 / 100 = 51%		
Parish: SABINE		PWSID: LA1085053		
2022 Water Grade				
Federal Water Quality	Treatment Tech		ım Contaminant	-30
State Water Quality	water operator,		disinfection, and	-1
Financial Sustainability	which can affect water system. A	I for lack of financ operations and main operations and main operations and future	intenance of the e can provide for	-10
Operations & Maintenance	deficiencies note	d for operation ar ed during water sys : the water quality bei	tem inspections,	-3
Infrastructure	during water sys	for infrastructure de stem inspections, wh vater and/or water se	nich may lead to	-0
Customer Satisfaction	the water systen Health, which ar	for customer compland and/or the Louisian reconfirmed to be a the water system.	a Department of	-10
Secondary Contaminants	greater than th levels. These lev	for levels of iron an e secondary maximi els do not pose a hea e water quality issues	um contaminant alth risk but may	-0
BONUS	storage assessm assessment & m		e program; well ; participation in	+5

www.ldh.la.gov/watergrade



2022 Water Grade Details BELMONT WATERWORKS INC

Standard	Standard Maximum	Point Deductions	Detailed Assessment of Standards				
Federal Water Quality		5 each	Maximum contaminant level violations	4			
	-30	5 each	Treatment technique violations for Lead and Copper Rule	0	- 30		
		10	Is the system non-compliant with an administrative order?	Yes			
State Water Quality	-10	1 each	Chlorine violations	1			
		5	Does the water System have an operator?	Yes	- 1		
		5 each	Water outages and/or boil notices	0			
Financial Sustainability		5	Did the system submit an acceptable rate study or implement an adequate rate?	No	- 10		
	-10	5	Did the water system submit an acceptable audit?	No			
	-10	10	Is the system under a fiscal administrator for poor financial management practices?	No			
		5	Are there other negative circumstances that affect fiscal control of the water system?	No			
Operations & Maintenance	-15	3 each	Unresolved significant deficiencies		- 3		
Infrastructure	-20	5 each	Unresolved significant deficiencies		- 0		
Customer Satisfaction -10	10	1 each	Valid water complaints reported	0	- 10		
	-10	10	Did the system submit a water complaint log?	No			
Secondary Contaminants	-5	5	Manganese and/or Iron level(s) over the secondary maximum contaminant level(s)		- 0		
Bonus	+10	5 each	Asset management plan, storage or well assessment & maintenance plan, participation in capacity development or management training	1	+ 5		
Total Deductions + Bonus							
Score							