Q	LOUISIANA DEPARTMEN Engineering Services	40 / 100 = 40%		
LELEUX TRAILER PARK WATER SYSTEM				
Parish: IBERIA PWSID: LA1045027				
2	023 Wate			
Federal Water Quality	Treatment Techr		n Contaminant	-10
State Water Quality	water operator,		isinfection, and	-4
Financial Sustainability	which can affect water system. An	for lack of financia operations and main effective water rate enance, and future N	tenance of the can provide for	-10
Operations & Maintenance	deficiencies note	for operation and d during water syste the water quality bein N	em inspections,	-6
Infrastructure	during water syst	for infrastructure def em inspections, which ater and/or water ser N	ch may lead to	-15
Customer Satisfaction	the water system	· · · · · · · · · · · · · · · · · · ·	Department of	-10
Secondary Contaminants	greater than the levels. These leve	for levels of iron and secondary maximu Is do not pose a heal water quality issues.	m contaminant th risk but may	-5
BONUS	storage assessme assessment & ma		program; well participation in	+0

www.ldh.la.gov/watergrade



## 2023 Water Grade Details LELEUX TRAILER PARK WATER SYSTEM

Standard	Standard Maximum	Point Deductions	Detailed Assessment of Standards				
Federal Water Quality		5 each	Maximum contaminant level violations	0			
	-30	5 each	Treatment technique violations for Lead and Copper Rule	0	- 10		
		10	Is the system non-compliant with an administrative order?	Yes			
State Water Quality	-10	1 each	Chlorine violations	4	- 4		
		5	Does the water system have an operator?	Yes			
		5 each	Water outages and/or boil notices	0			
Financial Sustainability		5	Did the system submit an acceptable rate study or implement an adequate rate?	No	10		
	-10	5	Did the water system submit an acceptable audit?	No			
	-10	10	Is the system under a fiscal administrator for poor financial management practices?	No	- 10		
		5	Are there other negative circumstances that affect fiscal control of the water system?	No			
Operations & Maintenance	-15	3 each	Unresolved significant deficiencies		- 6		
Infrastructure	-20	5 each	Unresolved significant deficiencies		- 15		
Customer Satisfaction -10	10	1 each	Valid water complaints reported	0	10		
	10	Did the system submit a water complaint log?	No	- 10			
Secondary Contaminants	-5	5	Manganese and/or Iron level(s) over the secondary maximum contaminant level(s)		- 5		
Bonus	+10	5 each	Asset management plan, storage or well assessment & maintenance plan, participation in capacity development or management training		+ 0		
Total Deductions + Bonus					-60		
Score					40 / 100 = 40%		